



## Product News

**Date:** 04/12/2011

**Revised:** 05/10/2011

**Subject:** Air Spring Service Assemblies

**Update Number:** 002

# NEW PRODUCT ANNOUNCEMENT

**Air Spring Service Assemblies for Select New Holland® Round Balers are Now Available.**

**Part Number:** QP857581

**Description:** Air Spring Service Assembly

**Make:** New Holland®

**Models:** \*855 and 858 Round Balers

\*855 models prior to S/N 733140 need the new style pistons (New Holland® part #695770) and retainer (New Holland® part #850097) for use with the air spring service assembly.



**Part Number:** QP857661

**Description:** Air Spring Service Assembly

**Make:** New Holland®

**Models:** 848 and 853 Round Balers



Air spring service assembly consists of the flex member, upper bead plate, lower retainer and locknut.

Quality Power Products - 427 Old Hwy 40 - Solomon, KS 67480  
1-888-333-3210